

Land at Frog Island

Photographic images of the Eastern Boundary of the Site, of the current situation and the suggested mitigation and enhancement measure of painting the existing shipping containers a similar colour to that of adjacent buildings. Enhanced with a small amount of additional evergreen tree / shrub planting.

Current Situation



Receptor 13 - Work place receptors in individual / work units off Ferry Lane, located opposite the Site, looking west towards the Site at a distance of ~60m

Proposed Mitigation / Enhancement Measures



Receptor 13 - Work place receptors in individual / work units off Ferry Lane, located opposite the Site, looking west towards the Site at a distance of ~60m

Land at Frog Island

Photographic images of the Eastern Boundary of the Site, of the current situation and the suggested mitigation and enhancement measure of painting the existing shipping containers a similar colour to that of adjacent buildings. Enhanced with a small amount of additional evergreen tree / shrub planting.

Current Situation



Receptor 14 - Work place receptors located off Ferry Lane located opposite the Site, looking west towards the Site at a distance of ~15m

Proposed Mitigation / Enhancement Measures



Receptor 14 - Work place receptors located off Ferry Lane located opposite the Site, looking west towards the Site at a distance of ~15m